



# TECHNICAL SERVICE BULLETIN

SERVICE DEPARTMENT • FORD DIVISION • FORD MOTOR COMPANY

## FIFTEEN MONTHS' INDEX COVERING PERIOD FROM OCTOBER 19, 1964 THROUGH JANUARY 28, 1966

### BODY

FORD CAR

Paint and Sheet Metal

Misaligned ash tray and glove box door  
Paint damage due to organic fallout  
Door edge protector used in transit  
Acrylic enamel usage  
Glove box door - hard opening  
Service paint color match  
Finish sanding of acrylic paint  
Paint chipping near bumper ends  
Acrylic enamel usage (supplements Article 127)  
Service paint color match  
Exterior paint type - identification (warranty plate review)  
Glove box door - hard opening  
Paint chips and rust at rocker mouldings

75  
90  
109  
127  
130  
330  
359  
386  
399  
415  
434  
514  
534

Soft Trim

Installation of floor pan deadener  
Bucket seat removal and repair  
Accelerator pedal interference with carpet  
Package tray trim rattles  
Missing seat trim buttons  
Gap at door and 1/4 panel trim  
Door windlace retention and appearance  
Second seat cushion retention  
Rear seat safety pad  
Landau cover ballooning and tearing  
Bucket seat back squeaks  
Station wagon spare wheel cover alignment  
Front door trim panel ornament loose  
Convertible top damage by #4 bow  
Bench type front seat sag  
Seat back covers torn at seat belt holes  
Ballooning of front seat cover  
Convertible top back window assemblies  
Collapsed headlinings  
Front seat cushion and back spring squeaks  
Spare wheel cover alignment (supplements Article 197)  
Auxiliary seat back floor panel deformation  
Sun visor release effort  
Vinyl top protective wax removal  
Excess trim cement  
Door arm rest - loose attachment  
Landau top cover installation procedure

4  
34  
99  
111  
120  
133  
144  
161  
162  
174  
194  
197  
230  
237  
272  
295  
333  
364  
387  
388  
422  
427  
484  
503  
510  
522  
547

Hardware

Roof side medallion loose  
Illegal entry into luggage compartment  
Excessive key efforts or inoperative lock cylinders  
Loose or misaligned mouldings (LTD Models)  
Unintentional lock out  
Front door lock out  
Bumper chrome peeling  
Door locks do not latch  
Deck lid spear moulding installation  
Front bumper license plate mounting  
Inoperative rear door lock (4 door models)  
Front door hinge squeaks  
Inadequate rear license plate attachment  
Bumper jack rattles  
Door locks do not latch  
Rear door safety lock rattle  
Station wagon tailgate support arm malfunction  
Outside door handle push button binds  
Reclining seat actuating handle rattles  
Use of coarse thread fasteners  
Seat track malfunction  
Door lock stricker bolt breakage  
Windshield upper moulding attachment revision

2  
13  
47  
55  
63  
72  
84  
97  
112  
123  
142  
143  
146  
149  
160  
163  
166  
193  
217  
263  
265  
287  
332

ARTICLE NO.

Malfunctioning tailgate manual window regulator handle  
Insufficient rear vision on remote control mirror (1965)  
Paint peeling from moldings  
Seat belt - short  
Dual action tailgate adjustment, station wagons  
Six-way power seat - reversed or abnormal movement  
Identification of bumper lower extensions  
Glove box door - hard opening  
Quarter panel letters  
Bumper wax removal  
Luggage compartment - illegal entry  
Station wagon tailgate - emergency opening procedure  
  
Glass and Glass Operating Mechanism  
Back window replacement using adhesive sealer  
Mottling on tempered glass  
Inoperative power operated tailgate window  
Windshield glass replacement  
Loose vent window  
Rear door glass rattles and loss of stability  
Front door window rattles and high operating effort  
Convertible rear window breakage  
Windshield and back lite service replacement  
Convertible top back window assemblies  
Station wagon tailgate - emergency opening procedure  
  
Wind Noise, Dust and Water Leaks  
Door weatherstrip retention  
Wind noise along cowl top  
Air and water leaks cowl sides  
Luggage compartment water leaks  
Rear vent rustling noise (LTD)  
General article on wind noise correction  
Windshield and backlight service replacement  
Fuel odor in luggage compartment  
Wind whistle at windshield garnish molding  
Wind noise - second seat area (station wagons)  
Water leaks - repair sealant  
Wind noise diagnosis procedure  
Water leak at windshield area  
  
Squeaks and Rattles  
Remote outside mirror rattles  
Body mount noise  
Package tray trim rattles  
License plate rattles  
Front door hinge squeaks  
Rear door glass rattle and loose stability  
Bumper jack rattle  
Rear door safety lock rattle  
Bucket seat back squeaks  
Reclining seat handle rattle  
Front door window rattles and/or high operating efforts  
Tailgate window rattle  
Rear vent rustling (LTD models)  
Wheel cover medallion rattles (1964-65)  
Front and Rear bumper rattles (all models)  
Loose rear shock absorber lower attachment  
Seat squeaks - bucket seat cushions (1964-65)  
Squeaks and creaking noise at bottom of rear door area (1965 station wagon)  
Squeaks and rattles station wagon second and third seat and auxiliary floor panels  
  
Body Electrical  
Six way power seat trouble shooting  
Ash tray light leakage  
Windshield washer accessory kit

341  
342  
343  
344  
397  
410  
496  
514  
544  
544  
550  
576  
  
28  
87  
129  
140  
141  
148  
219  
264  
270  
364  
576  
  
3  
85  
98  
167  
248  
261  
270  
377  
421  
441  
479  
527  
607  
  
54  
79  
111  
126  
143  
148  
149  
163  
194  
217  
219  
240  
248  
345  
369  
372  
402  
405  
459  
  
23  
116  
254

# BODY

## ARTICLE NO.

## ARTICLE NO.

### MUSTANG

#### Paint and Sheet Metal

|                                                                    |     |
|--------------------------------------------------------------------|-----|
| Convertible cowl shake .....                                       | 86  |
| Paint damage due to organic fallout .....                          | 90  |
| Door edge protectors used in transit .....                         | 109 |
| Acrylic enamel usage .....                                         | 127 |
| Paint peeling or flaking .....                                     | 273 |
| Vinyl tape accent stripe replacement .....                         | 310 |
| Service paint color match .....                                    | 330 |
| Finish sanding of acrylic paint .....                              | 359 |
| Paint adhesion on fiberglass interior panels .....                 | 394 |
| Acrylic enamel usage (supplements Article 127) .....               | 399 |
| Service paint color match .....                                    | 415 |
| Exterior paint type identification (warranty plate revision) ..... | 434 |
| Paint chipping .....                                               | 532 |
| Coach joint sealer repair .....                                    | 542 |

#### Soft Trim

|                                                  |     |
|--------------------------------------------------|-----|
| Adjustable passenger seat .....                  | 1   |
| Console modification for A/C installation .....  | 32  |
| Accelerator pedal interference with carpet ..... | 99  |
| Squeak and 1/4 trim damage on folding seat ..... | 137 |
| Convertible top damage .....                     | 199 |
| Elimination of shipping covers - vinyl top ..... | 349 |
| Excessive rearward tilt of front seat back ..... | 408 |
| Vinyl top protective wax removal .....           | 503 |
| Excess trim cement .....                         | 510 |
| Landau top cover installation procedure .....    | 547 |

#### Hardware

|                                                                |     |
|----------------------------------------------------------------|-----|
| High key efforts luggage compartment or lock out .....         | 22  |
| Excessive key effort or inoperative lock cylinder .....        | 47  |
| Front door lockout .....                                       | 72  |
| Bumper chrome peeling .....                                    | 84  |
| Seat track high operating efforts .....                        | 165 |
| Use of coarse thread fasteners .....                           | 263 |
| Seat track malfunction .....                                   | 265 |
| Seat track revision to gain additional leg room .....          | 269 |
| Seat belt hardware rattles (see correction dated 6-1-65) ..... | 278 |
| Door lock striker bolt breakage .....                          | 287 |
| Excessive rearward tilt of front seat back .....               | 408 |
| Bumper wax removal .....                                       | 544 |
| Deformation of door inside handle escutcheon plate .....       | 559 |

#### Glass and Glass Operating Mechanism

|                                                 |     |
|-------------------------------------------------|-----|
| Mottling in tempered glass .....                | 87  |
| High door window operating efforts .....        | 89  |
| Door rattles and window instability .....       | 92  |
| Quarter window rattle .....                     | 172 |
| Door window rattles and glass instability ..... | 214 |

#### Window Noise, Dust and Water Leaks

|                                                                                          |     |
|------------------------------------------------------------------------------------------|-----|
| Rear tail lamp water leak .....                                                          | 20  |
| Convertible water leaks at No. 1 roof bow .....                                          | 185 |
| Windshield and back window moulding water leaks .....                                    | 245 |
| Water leaks along the bottom of the courtesy lamp housing and the door inter panel ..... | 419 |
| Wind noise or wind whistle .....                                                         | 453 |
| Water leaks from behind the door trim panel .....                                        | 470 |
| Water leaks - repair sealant .....                                                       | 479 |
| Wind noise diagnosis procedure .....                                                     | 527 |

#### Squeaks and Rattles

|                                                                              |     |
|------------------------------------------------------------------------------|-----|
| Convertible top rattles .....                                                | 17  |
| Door lock remote control rod rattle .....                                    | 18  |
| Glove box door rattle .....                                                  | 44  |
| Remote lock button rattles .....                                             | 110 |
| Folding seat squeak and damage to trim panel .....                           | 137 |
| Quarter window rattle .....                                                  | 172 |
| Door window rattles and glass instability .....                              | 214 |
| Latch assembly, luggage compartment accessory door rattles .....             | 218 |
| Potential rattles emanating from radiator grille assembly .....              | 366 |
| Possible door rattles and damage to door courtesy lamp wiring assembly ..... | 390 |
| Front seat track latch tie rod interference and rattle .....                 | 393 |
| Spare tire rattle .....                                                      | 401 |

### FALCON

#### Paint and Sheet Metal

|                                                                         |     |
|-------------------------------------------------------------------------|-----|
| Paint damage due to organic fallout .....                               | 90  |
| Door edge protectors used in transit .....                              | 109 |
| Acrylic enamel usage .....                                              | 127 |
| Paint stains adjacent to rear lamps .....                               | 239 |
| Objectional protrusion of the rear door trim panel upper retainer ..... | 281 |
| Service paint color match .....                                         | 330 |

|                                                                    |     |
|--------------------------------------------------------------------|-----|
| Finish sanding of acrylic paint .....                              | 359 |
| Acrylic enamel usage (supplements Article 127) .....               | 399 |
| Service paint color match .....                                    | 415 |
| Exterior paint type identification (warranty plate revision) ..... | 434 |
| Coach joint sealer repair .....                                    | 542 |
| Fender to tire interference .....                                  | 551 |

#### Soft Trim

|                                                  |     |
|--------------------------------------------------|-----|
| Accelerator pedal interference with carpet ..... | 99  |
| Front door trim panel ornament loose .....       | 230 |
| Headlining discoloration .....                   | 274 |
| Sun visor release effort .....                   | 484 |
| Vinyl top protective wax removal .....           | 503 |
| Excess trim cement .....                         | 510 |
| Landau top cover installation procedure .....    | 547 |
| Insufficient package tray retention .....        | 561 |
| Front passenger bench seat rattles .....         | 604 |

#### Hardware

|                                                           |     |
|-----------------------------------------------------------|-----|
| Excessive key efforts or inoperative lock cylinders ..... | 47  |
| Front door lockout .....                                  | 72  |
| Bumper chrome peeling .....                               | 84  |
| Rear door safety lock rattle .....                        | 163 |
| Use of coarse thread fasteners .....                      | 263 |
| Seat track malfunctions .....                             | 265 |
| Door lock striker bolt breakage .....                     | 287 |
| Seat belt retractor breakage .....                        | 348 |
| Dual-action tailgate adjustment station wagon .....       | 397 |
| Bumper wax removal .....                                  | 544 |

#### Glass and Glass Operating Mechanism

|                                         |     |
|-----------------------------------------|-----|
| Mottling on tempered glass .....        | 87  |
| Potential tailgate glass breakage ..... | 337 |

#### Wind Noise, Dust and Water Leaks

|                                      |     |
|--------------------------------------|-----|
| Wind noise or wind whistle .....     | 453 |
| Water leaks - repair sealant .....   | 479 |
| Wind noise diagnosis procedure ..... | 527 |
| Water leak - antenna hole .....      | 609 |

#### Squeaks and Rattles

|                                                               |     |
|---------------------------------------------------------------|-----|
| Glove box door rattle .....                                   | 44  |
| Rear door safety lock rattle .....                            | 163 |
| Squeaks and rattles emanating from the instrument panel ..... | 336 |
| Front bench seat rattles .....                                | 604 |

### FAIRLANE

#### Paint and Sheet Metal

|                                                                    |     |
|--------------------------------------------------------------------|-----|
| Paint damage due to organic fallout .....                          | 90  |
| Door edge protectors used in transit .....                         | 109 |
| Acrylic enamel usage .....                                         | 127 |
| Service paint color match .....                                    | 330 |
| Finish sanding of acrylic paint .....                              | 359 |
| Acrylic enamel usage (supplements Article 127) .....               | 399 |
| Service paint color match .....                                    | 415 |
| Exterior paint type identification (warranty plate revision) ..... | 434 |
| Coach joint sealer repair .....                                    | 542 |
| Fender to tire interference .....                                  | 551 |
| Insufficient package tray retention .....                          | 561 |

#### Soft Trim

|                                                  |     |
|--------------------------------------------------|-----|
| Accelerator pedal interference with carpet ..... | 99  |
| Sun visor release effort .....                   | 484 |
| Vinyl top protective wax removal .....           | 503 |
| Excess trim cement .....                         | 510 |
| Folded top too high in stacked position .....    | 546 |
| Landau top cover installation .....              | 547 |
| Front door trim panel rattles .....              | 600 |
| Front passenger bench seat rattles .....         | 604 |

#### Hardware

|                                                           |     |
|-----------------------------------------------------------|-----|
| Excessive key efforts or inoperative lock cylinders ..... | 47  |
| Front door lockout .....                                  | 72  |
| Bumper chrome peeling .....                               | 84  |
| Rear door safety lock rattle .....                        | 163 |
| Use of coarse thread fasteners .....                      | 263 |
| Seat track malfunction .....                              | 265 |
| Rear door lock problems .....                             | 271 |
| Door lock striker bolt breakage .....                     | 287 |
| Dual-action tailgate adjustment - station wagons .....    | 397 |
| Bumper wax removal .....                                  | 544 |
| Luggage compartment - illegal entry .....                 | 550 |

#### Glass and Glass Operating Mechanism

|                                            |     |
|--------------------------------------------|-----|
| Mottling in tempered glass .....           | 87  |
| Malfunction of the front door window ..... | 531 |

Wind Noise, Dust and Water Leaks

|                                                            |     |
|------------------------------------------------------------|-----|
| Water leaks and wind noise at roof rail weatherstrip ..... | 436 |
| Wind whistle or wind noise .....                           | 453 |
| Water leaks - repair sealant .....                         | 479 |
| Wind noise diagnosis procedure .....                       | 527 |
| Water leak - antenna hole .....                            | 609 |
| Fuel odors in passenger compartment .....                  | 611 |

Squeaks and Rattles

|                                                               |     |
|---------------------------------------------------------------|-----|
| Remote outside mirror rattle .....                            | 54  |
| Rear door safety lock rattle .....                            | 163 |
| Squeaks and rattles emanating from the instrument panel ..... | 336 |
| Front door trim panel rattles .....                           | 600 |
| Front passenger bench seat rattles .....                      | 604 |

THUNDERBIRDPaint and Sheet Metal

|                                                                   |     |
|-------------------------------------------------------------------|-----|
| Paint damage due to organic fallout .....                         | 90  |
| Door edge protectors used in transit .....                        | 109 |
| Acrylic enamel usage .....                                        | 127 |
| Service paint color match .....                                   | 330 |
| Quarter panel wheel opening cover misalignment (1964-65) .....    | 338 |
| Finish sanding of acrylic paint .....                             | 359 |
| Acrylic enamel usage (supplements Article 127) .....              | 399 |
| Service paint color match .....                                   | 415 |
| Exterior paint type identification (warranty plate revised) ..... | 434 |

Soft Trim

|                                                  |     |
|--------------------------------------------------|-----|
| Back curtain of zipper replacement .....         | 42  |
| Accelerator pedal interference with carpet ..... | 99  |
| Vinyl material squeaks .....                     | 173 |
| Landau cover ballooning and tearing .....        | 174 |
| Bucket seat backs squeak .....                   | 194 |
| Package tray area squeaks - 1964-65 .....        | 329 |
| Elimination of shipping covers (vinyl top) ..... | 349 |
| Vinyl top protective wax removal .....           | 503 |
| Excess trim cement .....                         | 510 |
| Landau top cover installation .....              | 547 |

Hardware

|                                                                 |     |
|-----------------------------------------------------------------|-----|
| Excessive key efforts or inoperative lock cylinders .....       | 47  |
| Unintentional lockout .....                                     | 63  |
| Front door lockout .....                                        | 72  |
| Front door hinge squeaks .....                                  | 143 |
| Reclining seat actuating handle rattles .....                   | 217 |
| Use of coarse thread fasteners .....                            | 263 |
| Seat track malfunctions .....                                   | 265 |
| Rattle between folding top control link & front side rail ..... | 285 |
| Door lock striker bolt breakage .....                           | 287 |
| Deformation of door inside handle escutcheon plate .....        | 559 |

Glass and Glass Operating Mechanism

|                                            |     |
|--------------------------------------------|-----|
| Mottling in tempered glass .....           | 87  |
| Door window rattles in down position ..... | 216 |

Wind Noise, Dust and Water Leaks

|                                                     |     |
|-----------------------------------------------------|-----|
| Luggage and passenger compartment water leaks ..... | 266 |
| Water leaks in luggage compartment .....            | 461 |
| Water leaks - repair sealant .....                  | 479 |
| Wind noise diagnosis procedure .....                | 527 |

Squeaks and Rattles

|                                                      |     |
|------------------------------------------------------|-----|
| Remote outside mirror rattle .....                   | 54  |
| Front door hinge squeaks .....                       | 143 |
| Trim material squeaks - vinyl .....                  | 173 |
| Bucket seat back squeaks .....                       | 194 |
| Door window rattles in down position .....           | 216 |
| Reclining seat handle rattles .....                  | 217 |
| Package tray area squeaks (1964-65) .....            | 329 |
| Seats Squeaks - bucket seat cushions (1964-65) ..... | 402 |

TRUCKBronco & Ranchero

|                                                                                    |     |
|------------------------------------------------------------------------------------|-----|
| Windshield frame mounting bolts cross thread .....                                 | 581 |
| Water leaks (Bronco) .....                                                         | 588 |
| Water leaks (Ranchero) .....                                                       | 590 |
| Front passenger bench seat rattles (Ranchero) .....                                | 604 |
| Water entrapment in floor pan (Bronco) .....                                       | 606 |
| Potential water leaks around cover plate on the rear corner pillars (Bronco) ..... | 610 |

Econoline

|                                                          |     |
|----------------------------------------------------------|-----|
| Difficult minor installation (Western Type Mirror) ..... | 67  |
| Windshield wiper bracket failure .....                   | 159 |
| Door lock cylinder lubrication .....                     | 202 |
| Exterior paint type identification .....                 | 434 |

Light

|                                                              |     |
|--------------------------------------------------------------|-----|
| Difficult mirror installation (Western Type Mirror) .....    | 67  |
| Seat back angle (65 Conventional cab with bench seats) ..... | 183 |
| Door lock cylinder lubrication .....                         | 202 |
| Pick up box splitting .....                                  | 289 |
| Body equipment installation precautions .....                | 296 |
| Mud and snow splash in engine compartment .....              | 335 |
| Exterior paint type identification .....                     | 434 |
| Insufficient hand access to release hood safety catch .....  | 494 |

Medium

|                                                                |     |
|----------------------------------------------------------------|-----|
| Difficult mirror installation (Western Type Mirror) .....      | 67  |
| Seat back angle (1965 Conventional cab with bench seats) ..... | 183 |
| Door lock cylinder lubrication .....                           | 202 |
| Body equipment installation precautions .....                  | 296 |
| Breakage of fenders, aprons and brackets .....                 | 347 |
| Exterior paint type identification .....                       | 434 |
| Insufficient hand access to release hood safety catch .....    | 494 |

Heavy - Extra Heavy

|                                                                       |     |
|-----------------------------------------------------------------------|-----|
| Difficult mirror installation (Western Type Mirror) .....             | 67  |
| Cab and/or sleeper breakage (1962-64 C & H Series) .....              | 131 |
| Seat back angle (1965 Conventional cab with bench seats) .....        | 183 |
| Door lock cylinder lubrication .....                                  | 202 |
| Body equipment installation precautions .....                         | 296 |
| Breakage of fenders, aprons and brackets .....                        | 347 |
| Excessive cab tilting effort .....                                    | 406 |
| Exterior paint type identification .....                              | 434 |
| Insufficient hand access to release hood safety catch .....           | 494 |
| Front panel corrosion due to water being entrapped under emblem ..... | 518 |
| Cab sheet metal failure at upper exhaust pipe mounting bracket .....  | 529 |
| Aluminum sleeper compartment failure .....                            | 596 |

**PASSENGER CAR CHASSIS & POWERTRAIN**Front & Rear Suspension, Steering, Wheels & Tires

|                         |                                                                                 |          |
|-------------------------|---------------------------------------------------------------------------------|----------|
| All Car Lines           | - New power steering pump hiss .....                                            | 25       |
| All Car Lines           | - New power steering pump leaks .....                                           | 106      |
| All Car Lines           | - Hoisting precaution .....                                                     | 312      |
| All Car Lines           | - Ford-Thompson power steering pumps (Repair of) .....                          | 414      |
| All Car Lines           | - Application of remanufactured Ford-Thompson power steering pumps .....        | 424      |
| All Car Lines           | - Power steering pump oil leaks .....                                           | 425      |
| Ford                    | - Ford with Saginaw gear and fixed column - noise complaint ..                  | 26       |
| Ford                    | - Safety stand placement .....                                                  | 46       |
| Ford                    | - Front suspension noise (also see part number correction in Issue No. 7) ..... | 91       |
| Ford                    | - Power steering oil cooler .....                                               | 117      |
| Ford                    | - RPO Wire wheel cover installation ..                                          | 121      |
| Ford                    | - Rear suspension pivot bolts and nuts .....                                    | 139      |
| Ford                    | - Station wagon tire pressures .....                                            | 156      |
| Ford                    | - Power steering idle compensator ..                                            | 191      |
| Ford                    | - Station wagon sway .....                                                      | 188, 234 |
| Ford                    | - Steering column grommet interference with power brake pedal .....             | 244      |
| Ford                    | - Rear shock absorber noise .....                                               | 256      |
| Ford                    | - High steering efforts with power steering .....                               | 360      |
| Ford                    | - Loose rear shock lower attachment .....                                       | 372      |
| Ford                    | - Wheel identification .....                                                    | 378      |
| Ford (XL, LTD, 7 Litre) | - Styled wheel cover installation .....                                         | 420      |
| Fairlane                | - Steering column shaft tube replacement .....                                  | 316      |
| Mustang & Thunderbird   | - Dynamically balancing wheel and tires on disc brake units .....               | 56       |
| Mustang                 | - RPO Special handling package .....                                            | 107      |
| Mustang                 | - Spare tire rattle .....                                                       | 401      |
| Ford                    | - Front wheel alignment specifications .....                                    | 498      |
| Ford                    | - High power steering efforts at sustained high speed driving .....             | 502      |
| '65 T-Bird              | - Lean to left .....                                                            | 520      |
|                         | - Defective shock absorber diagnosis ..                                         | 523      |
|                         | - Frame failures (off-the-road operation) ..                                    | 549      |
|                         | - Fender to tire interference (Falcon, Fairlane) ..                             | 551      |
|                         | - Steering wheel removal .....                                                  | 567      |
|                         | - Suspension torque specifications .....                                        | 586      |

**PASSENGER CAR****CHASSIS & POWERTRAIN - (Cont'd.)**Exhaust System

|         |                                                            |     |
|---------|------------------------------------------------------------|-----|
| Mustang | - High noise level of "Arvinode" dual exhaust system ..... | 315 |
| Mustang | - Dual exhaust system (65-1/2 289 4V H. P.) .....          | 328 |
| Mustang | - Single exhaust system noise (65 289 4V) .....            | 358 |
| Falcon  | - Exhaust boom noise .....                                 | 558 |
| T-Bird  | - Backfire on deceleration .....                           | 573 |

Axle & Driveline

|      |                                                                                                            |     |
|------|------------------------------------------------------------------------------------------------------------|-----|
| Ford | - Axle lubricant leak through vent hose .....                                                              | 33  |
|      | Equalock axle service identification tag .....                                                             | 41  |
|      | High speed driveline vibrations .....                                                                      | 104 |
|      | All cars with demountable axle carriers - pinion gear and hub failures on locking differential axles ..... | 340 |
|      | Rear axle - revision to method of setting pinion bearing .....                                             | 407 |
|      | Driveshaft balancing identification .....                                                                  | 416 |
|      | Driveshaft yoke spline lubricant .....                                                                     | 473 |
| Ford | - Rear axle vent installation .....                                                                        | 482 |

Automatic Transmission

|                        |                                                                                       |     |
|------------------------|---------------------------------------------------------------------------------------|-----|
| C4 Transmission        | - oil cooler hose leakage .....                                                       | 12  |
|                        | List of auto. trans. fluids which meet Ford Specs. ....                               | 155 |
| C4 Transmission        | - termination of exchange program .....                                               | 178 |
| C4 Transmission        | - oil pan gasket leakage caused by oil pan deformation .....                          | 198 |
| Ford                   | - High pitched buzzing or grinding noise due to improperly machined C-O-M parts ..... | 215 |
| 64 Ford                | - Manual linkage wear causing automatic transmission failures .....                   | 235 |
|                        | Automatic transmissions - special crowfoot wrench for vacuum T. V. diaphragm .....    | 280 |
| C-4 transmission       | gasket and oil seal kit (C4AZ-7153-C) .....                                           | 400 |
| Automatic transmission | - approved fluid list (revision) .....                                                | 413 |
|                        | Band adjusting screw locknut (C4 and C6) .....                                        | 513 |
|                        | GT type C6 three speed automatic transmission .....                                   | 515 |
|                        | Valve body spring identification (C4) .....                                           | 545 |
|                        | Gear shift lever and/or steering column rattle .....                                  | 557 |
| '66 T-Bird             | - Erratic and/or harsh or soft engagement .....                                       | 571 |

Clutch

|                              |                                                                      |     |
|------------------------------|----------------------------------------------------------------------|-----|
| 65 Mustang & 64 Fairlane     | - clutch pedal height .....                                          | 5   |
| 63 & 64 Ford Police and Taxi | - failure of swivel insulator at clutch pedal to equalizer rod ..... | 14  |
| Clutch                       | - High pedal efforts or scrubby pedal condition .....                | 385 |
| Clutch                       | - high pedal efforts or scrubby pedal .....                          | 556 |
| 1965-66 Ford                 | clutch adjustments .....                                             | 569 |

Manual Transmission

|                |                                                          |     |
|----------------|----------------------------------------------------------|-----|
| Mustang        | - 3-speed transmission shift lever noise .....           | 27  |
| Ford           | - Looseness in steering column and shift lever hub ..... | 71  |
| Mustang        | - High shift efforts .....                               | 213 |
| Transmission   | shift lever buzz - 1965 Mustang .....                    | 449 |
| Additional 303 | transmission gear ratios .....                           | 450 |
| Warner gear    | four-speed manual transmission .....                     | 451 |
| Reverse gear   | jumpout .....                                            | 507 |
| Mustang        | - gear shift selector lever replacement .....            | 560 |

Brakes

|                        |                                                                                                               |     |
|------------------------|---------------------------------------------------------------------------------------------------------------|-----|
| Disc brake creep       | - groan noise .....                                                                                           | 105 |
| Disc brake units       | - obtaining a firm brake pedal after servicing .....                                                          | 134 |
| Disc brake units       | - rotor hub bolt replacement .....                                                                            | 179 |
| Disc brake units       | - front wheel bearing end play adjustment .....                                                               | 311 |
| Power brake            | clunk noise during normal to quick brake application .....                                                    | 313 |
| Ford with power brakes | - hood splash rusting linkage* .....                                                                          | 317 |
| All drum brakes        | - brake adjustment procedure with new metal knockout plugs (also see supplement in July 2, 1965, issue) ..... | 327 |
| 65 T-Bird              | - Squeal noise on light brake pedal application .....                                                         | 346 |
| 65 Ford                | - Rear brake drag and/or early lining wear .....                                                              | 350 |
| Thunderbird            | - Road splash rusting power brake linkage* .....                                                              | 362 |

|                              |                                                                                          |     |
|------------------------------|------------------------------------------------------------------------------------------|-----|
| Thunderbird                  | - Servicing the brake booster assembly less master cylinder on disc brake vehicles ..... | 365 |
| Ford                         | - Incorrect brake shoe and lining assemblies in brake lining service kits .....          | 373 |
| Conversion of automatic      | adjusting brakes to manual adjustment brakes .....                                       | 383 |
| Disc brakes                  | - torque revision .....                                                                  | 438 |
| Part number and nomenclature | correction 1966 Ford Shop Manual .....                                                   | 446 |
| Power brake equipped Fords   | - boot installed incorrectly permitting engine noise in passenger compartment .....      | 563 |
| Disc brake units             | - rotor resurfacing .....                                                                | 575 |
| Disc brake torques           | .....                                                                                    | 583 |

\* (Also see revision in July 26, 1965 issue)

\* (Also see revisions in August 20, 1965 issue)

Fuel Tank & Lines

|                                              |                                        |     |
|----------------------------------------------|----------------------------------------|-----|
| Nylon fuel tube                              | - fuel tank to pump .....              | 431 |
| Anti-surge valve                             | in fuel tank vent system (Fairlane) .. | 504 |
| Fuel sender assembly                         | (Falcon & Fairlane) .....              | 506 |
| Fuel tank strap                              | - channel reinforcement .....          | 533 |
| Gasoline odors entering vehicle              | - 1966 Ford .....                      | 535 |
| Flexible (rubber) fuel hose                  | rubbs on fuel pump outlet tube .....   | 537 |
| Fuel leaks or odors in passenger compartment | (Fairlane) .....                       | 611 |

**TRUCK CHASSIS & POWERTRAIN**Front & Rear Suspension, Steering, Wheels & TiresBRONCO

|                                    |       |     |
|------------------------------------|-------|-----|
| Toe-in specifications              | ..... | 444 |
| Towing and lift instructions       | ..... | 471 |
| Defective shock absorber diagnosis | ..... | 523 |

ECONOLINE

|                                         |                                 |     |
|-----------------------------------------|---------------------------------|-----|
| Proper hoisting technique for Econoline | front end .....                 | 15  |
| Steering wheel installation             | .....                           | 209 |
| Tire and wheel runout specs.            | (All stamped disc wheels) ..... | 210 |
| Front axle                              | - spindle looseness .....       | 339 |
| Defective shock absorber diagnosis      | .....                           | 523 |

LIGHT

|                                           |                                 |     |
|-------------------------------------------|---------------------------------|-----|
| 1965 Front wheel alignment specifications | .....                           | 31  |
| Tire noise (rumbling noise or roar)       | .....                           | 81  |
| New rear wheel grease retainer            | (Spicer Model 60) .....         | 195 |
| Steering wheel installation               | .....                           | 209 |
| Tire and wheel runout specs.              | (All stamped disc wheels) ..... | 210 |
| Front axle                                | - spindle looseness .....       | 339 |
| Revised tire pressures                    | .....                           | 489 |

MEDIUM

|                                                      |                                                                 |     |
|------------------------------------------------------|-----------------------------------------------------------------|-----|
| 1965 Front wheel alignment specifications            | .....                                                           | 31  |
| Eaton axle cover oil leaks                           | .....                                                           | 95  |
| New six hole disc wheels (F, N, C, B-500-800 series) | .....                                                           | 115 |
| Rear spring seat cap bending (Eaton)                 | .....                                                           | 157 |
| Steering wheel installation                          | .....                                                           | 209 |
| Eaton axle differential kit                          | ..... 299, 391, 476                                             |     |
| Eaton axle                                           | - new pinion bearing cage casting (1964 and prior models) ..... | 358 |
| Front wheel spindle pin bushing                      | .....                                                           | 361 |
| Tire interference                                    | - inner to outer .....                                          | 418 |
| Eaton axle ring gear looseness                       | .....                                                           | 499 |
| Steering returnability                               | .....                                                           | 580 |
| Front spring shackle bracket side wear               | .....                                                           | 599 |

HEAVY & EXTRA HEAVY

|                                                      |                                                               |     |
|------------------------------------------------------|---------------------------------------------------------------|-----|
| 1965 Front wheel alignment specifications            | .....                                                         | 31  |
| Eaton axle cover oil leaks                           | .....                                                         | 95  |
| New six hole disc wheels (F, N, C, B-500-800 series) | .....                                                         | 115 |
| Rear spring seat cap bending (Eaton)                 | .....                                                         | 157 |
| Steering wheel installation                          | .....                                                         | 209 |
| Eaton axle differential kit                          | ..... 299, 391, 476                                           |     |
| Approved Hendrickson walking beam bushing            | .....                                                         | 301 |
| Hard steering                                        | - 1963-64 with manual steering and Super Duty or Diesel ..... | 352 |
| Eaton axle                                           | - new pinion bearing cage casting .....                       | 358 |
| Front wheel spindle pin bushings                     | .....                                                         | 361 |
| Tire interference                                    | - inner to outer .....                                        | 418 |
| Insufficient right turn C & CT series                | .....                                                         | 495 |
| Eaton axle                                           | - ring gear looseness .....                                   | 499 |
| Steering returnability                               | .....                                                         | 580 |
| Wheel shimmy and/or power steering failure           | .....                                                         | 602 |

**TRUCK CHASSIS & POWERTRAIN — (Cont'd.)****Brakes****LIGHT**

|                                                         |     |
|---------------------------------------------------------|-----|
| Master cylinder brake tube interference (F100/250)..... | 113 |
| Intermittent loss of brake pressure .....               | 292 |
| Revised brake adjustment procedure .....                | 327 |
| Brake pull, swerve or fade.....                         | 354 |
| Brake pull .....                                        | 423 |
| Brake drag (power brake units).....                     | 603 |

**MEDIUM**

|                                                                          |     |
|--------------------------------------------------------------------------|-----|
| New synchro-valve (Tractor-trailer air brake package).....               | 83  |
| Intermittent loss of brake pressure .....                                | 292 |
| Rear brake carrier plate attaching bolt failures (Hydraulic brakes)..... | 355 |
| Overheating or dragging brakes (Cowl mounted booster) .....              | 485 |
| Parking brake lever.....                                                 | 543 |

**HEAVY & EXTRA HEAVY**

|                                                                          |     |
|--------------------------------------------------------------------------|-----|
| New synchro-valve (Tractor-trailer air brake package).....               | 83  |
| Rear brake carrier plate attaching bolt failure (hydraulic brakes) ..... | 355 |
| Air compressor governor tube failure.....                                | 395 |
| Overheating or dragging brakes (cowl mounted booster).....               | 485 |

**Clutch, Transmission and Driveline****ECONOLINE**

|                                                                                                |     |
|------------------------------------------------------------------------------------------------|-----|
| C4 transmission intermediate servo piston and cover identification (Econoline & F series)..... | 51  |
| Driveline rating code patent plate revisions (Econoline) .....                                 | 53  |
| Universal joint maintenance .....                                                              | 433 |
| Gear rattle - three speed transmission.....                                                    | 490 |

**LIGHT**

|                                                                                                |          |
|------------------------------------------------------------------------------------------------|----------|
| Driveline, vibration 50-85 mph (F series) .....                                                | 16       |
| C4 transmission intermediate servo piston and cover identification (Econoline & F series)..... | 51       |
| Clutch shudder in low and reverse (F100/250).....                                              | 82       |
| Torsional vibration (223 CID units).....                                                       | 153      |
| Lubrication of New Process 4-speed and Ford 3-speed transmissions.....                         | 171      |
| New Process 4-speed, hard shifting first or second gear .....                                  | 229      |
| Transmission shift fork noise (F100/350 w/New Process trans.) .....                            | 233      |
| Torsional vibration - 4 speed transmission .....                                               | 300      |
| Torsional vibration - 352 CID .....                                                            | 334      |
| Gear rattle and shift fork noise .....                                                         | 382, 439 |
| Universal joint maintenance.....                                                               | 433      |
| Clutch shudder - low or reverse - 352 CID .....                                                | 474      |
| Reverse gear jumpout .....                                                                     | 507      |
| Clutch shudder in low and reverse.....                                                         | 553      |

**MEDIUM**

|                                              |     |
|----------------------------------------------|-----|
| Eaton axle cover oil leaks.....              | 95  |
| 16802 Eaton axle differential kit* .....     | 299 |
| Universal joint maintenance.....             | 433 |
| New 12" and 13" clutch disc assemblies ..... | 442 |
| Clutch release lever yoke breakage .....     | 478 |
| Eaton axle ring gear looseness**.....        | 499 |
| Power divider input shaft bearing .....      | 522 |
| Eaton axle 2-speed solenoid.....             | 565 |
| Eaton axle ring gear looseness .....         | 593 |
| Hard shifting - neutral to second.....       | 612 |

\* Also see revision in article 476

\*\* Also see revision in article 593

**HEAVY & EXTRA HEAVY**

|                                                            |     |
|------------------------------------------------------------|-----|
| Eaton axle cover oil leaks .....                           | 95  |
| Allison transmatic transmission exchange program .....     | 211 |
| Driveshaft alignment angles and phasing (65 Tandems) ..... | 250 |
| 16802 Eaton axle differential kit* .....                   | 299 |
| Universal joint maintenance.....                           | 433 |
| Oil loss through filler tube - Allison Transmatic .....    | 491 |
| Eaton axle ring gear looseness**.....                      | 499 |
| Eaton tandem air shift units.....                          | 524 |
| Three speed axle solenoids .....                           | 539 |
| Power divider input shaft bearing .....                    | 552 |
| Eaton axle 2-speed solenoid.....                           | 565 |

|                                       |     |
|---------------------------------------|-----|
| Eaton axle ring gear looseness.....   | 593 |
| Hard shifting neutral to second ..... | 612 |

\* Also see revision in article 476

\*\* Also see revision in article 593

**Frame****LIGHT**

|                                               |     |
|-----------------------------------------------|-----|
| Engine rear crossmember bolts loosening ..... | 288 |
|-----------------------------------------------|-----|

**HEAVY & EXTRA HEAVY**

|                                                           |     |
|-----------------------------------------------------------|-----|
| New No. 4 crossmember - Hendrickson Suspension.....       | 462 |
| Relocate No. 4 crossmember - Page & Page Suspension ..... | 467 |

**Fuel Systems**

|                                                                   |     |
|-------------------------------------------------------------------|-----|
| Fuel solenoid control mounting bracket failure (Dag. Diesel)..... | 591 |
|-------------------------------------------------------------------|-----|

**PASSENGER CAR - ELECTRICAL****Charging System**

|                                                                                                 |         |
|-------------------------------------------------------------------------------------------------|---------|
| Buzzing sound originating from G. P. D. Alternator Regulator (All Cars) .....                   | 78, 262 |
| Failed G. P. D. Alternator Regulators caused by wiring defects .....                            | 177     |
| Incorrect Alternator and Power Steering Mounting Bracket installation All with 289 engine ..... | 187     |
| 1965 Autolite Alternator rectifier Assembly Replacement.....                                    | 212     |
| Alternator belt rubs A/C idler pulley (240 engine).....                                         | 252     |
| Broken brush holder attaching screw - G. P. D. Alternators .....                                | 298     |
| Proper grounding of battery cable (Ford Fairlane, Falcon & Mustang with 289 engine).....        | 314     |
| Diagnosis of obscure alternator system malfunctions .....                                       | 324     |
| Mustang - Malfunctioning Ammeter .....                                                          | 326     |
| Autolite alternators with internal radio noise suppression capacitor (condenser).....           | 429     |
| Revised Alternator/water pump drive belts .....                                                 | 432     |
| All Cars - Accessory Drive Belts.....                                                           | 481     |

**Starting System**

|                                                                            |     |
|----------------------------------------------------------------------------|-----|
| All Cars - Starter Drive failures .....                                    | 154 |
| Mustang - Relay to Starter Cable .....                                     | 158 |
| All Cars with 289 Engines - Proper grounding of battery ground cable ..... | 314 |
| Thunderbird - Hard Starting - Cable acid damage .....                      | 483 |

**Ignition System**

|                                                        |     |
|--------------------------------------------------------|-----|
| All Cars - Distributor Cam Lubricant .....             | 10  |
| All Cars - Ignition System Specification Changes ..... | 125 |
| All Cars - Ignition Contact Replacement .....          | 147 |
| Transistor Ignition System Schematic Error .....       | 277 |
| Spark Plug Usage - 240 & 289 Engines .....             | 371 |
| Ford 352 & 390 - Pinched Secondary Wires .....         | 374 |
| Fairlane 390GT - Distributor Advance Curve .....       | 412 |
| All Cars - Revised timing specifications .....         | 579 |

**Lamps and Body Wiring**

|                                                                                     |     |
|-------------------------------------------------------------------------------------|-----|
| Fairlane - Headlight removal and installation .....                                 | 35  |
| Ford - Interior bulbs (turn signal, high beam, speedometer) .....                   | 36  |
| All Cars - Bullet terminal removal from turn signal switch multiple connector ..... | 77  |
| Ford - Ash tray light leakage .....                                                 | 116 |
| Fairlane - Intermittent operation of horns, parking lamps and rear lamps .....      | 152 |
| Ford - Back-up lamp switch kit .....                                                | 242 |
| Fairlane - Interference of windshield wiper linkage to main wiring loom .....       | 243 |
| Fairlane - Headlight failure prevention .....                                       | 251 |
| Mustang - Rear lamp extension wiring .....                                          | 255 |
| T-Bird - Main body wiring harness chafing at brake pedal support.....               | 267 |
| T-Bird - Breakage of seat belt warning lamp lens*.....                              | 275 |
| All Cars - Instrument panel bulb replacement.....                                   | 284 |
| All except T-Bird-Emergency Warning flasher system operation.....                   | 293 |
| Potential fog lamp bulb breakage (Mustang)** .....                                  | 297 |
| Inoperative or erratic horn operation .....                                         | 302 |
| Ford - Parking lamp water entry and corrosion (1965).....                           | 331 |
| Mustang - Potential fog lamp breakage .....                                         | 398 |
| Seat belt warning light operation (all car lines).....                              | 435 |

**PASSENGER CAR - ELECTRICAL - (Cont'd.)**

|                                                                      |     |
|----------------------------------------------------------------------|-----|
| Electrical feedback during emergency warning flasher operation ..... | 492 |
| Headlamp retention and adjustment .....                              | 597 |
| Ford - Improper installation of dimmer switch .....                  | 605 |

\* (also see Revision in July 2, 1965 issue)

\*\* (see Revision in Sept. 3, 1965 issue)

**Instruments, Indicators and Equipment**

|                                                                                     |     |
|-------------------------------------------------------------------------------------|-----|
| All Cars - Speedometer cable hex head nut wrench .....                              | 8   |
| All Cars - Bullet terminal removal from turn signal switch multiple connector ..... | 77  |
| T-Bird - Speedometer cable routing .....                                            | 80  |
| All Cars - Disconnected speedometer cable .....                                     | 103 |
| All Cars - Malfunction of turn signal switch .....                                  | 118 |
| Falcon - Erratic windshield wiper operation .....                                   | 150 |
| Fairlane - Intermittent operation of horns, parking lamps and rear lamps .....      | 152 |
| Ford - Low fuel level warning system .....                                          | 168 |
| Mustang - Windshield wiper motor removal and installation procedure .....           | 175 |
| T-Bird - Adjustment of hydraulic windshield wiper motor control cable .....         | 192 |
| Fairlane & Ford - Speedometer driven gear ticking noise .....                       | 200 |
| Mustang - Illumination of PRNDL dial for daytime visibility .....                   | 201 |
| Ford - Instrument cluster lens dirty and fogged .....                               | 236 |
| Mustang - Fuel gage reads full .....                                                | 246 |
| Fairlane - Interference of windshield wiper linkage to main wiring loom .....       | 243 |
| T-Bird - Breakage of seat belt warning lamp lens .....                              | 275 |
| All except T-Bird - Emergency warning flasher system operation .....                | 293 |
| All Cars - Horn replacement .....                                                   | 294 |
| Speed Control (1965 Ford) .....                                                     | 309 |
| Mustang - Malfunctioning Ammeter .....                                              | 326 |
| T-Bird - Headlamp switch failure .....                                              | 356 |
| All Cars - Speedometer system complaints .....                                      | 376 |
| Windshield wiper park switch adjustment (single speed) .....                        | 392 |
| All except Mustang - Speedometer driven gear replacement .....                      | 443 |
| Turn Signal Problem Diagnosis .....                                                 | 454 |
| All Cars - Speedometer ticking noise .....                                          | 497 |
| All Cars - Horn button removal .....                                                | 567 |
| All except T-Bird - Windshield washer pump operation .....                          | 574 |
| All except T-Bird - Horn will not blow .....                                        | 582 |

**Radio and Electrical Accessories**

|                                                          |     |
|----------------------------------------------------------|-----|
| Ford - 6-way power seats .....                           | 23  |
| Ford - Speed control .....                               | 73  |
| Ford - Back-up lamp switch kit .....                     | 242 |
| All Cars - 1965 rear seat speaker kit wiring .....       | 258 |
| Rear speaker Studiosonic boom or "bongo" noise* .....    | 357 |
| Ford - Windshield washer pump .....                      | 375 |
| Rotunda auto radio test tool .....                       | 389 |
| Six-way power seat - reversed or abnormal movement ..... | 410 |
| Stereo tape player .....                                 | 505 |
| Stereo tape player clicking or popping .....             | 595 |

\* (Also see supplement in August 20, 1965 issue)

**Heater, Defroster and A/C**

|                                                                               |     |
|-------------------------------------------------------------------------------|-----|
| 64 Economy A/C - Customer complaint of "no heat" .....                        | 19  |
| 64 Ford & T-Bird - A/C vibration problems .....                               | 29  |
| 65 Ford - A/C control chart .....                                             | 136 |
| 65 Ford - Integral heater - A/C system malfunction .....                      | 145 |
| Ford - A/C and heating control assembly .....                                 | 164 |
| Fairlane - Heater control adjustment .....                                    | 253 |
| Heater core removal and installation (with or without air conditioning) ..... | 305 |
| Poor defrost pattern (1965 Fairlane all models) .....                         | 321 |
| Air Conditioner Vibration or Moan (30-38 mph) .....                           | 363 |
| Evaporator condensate leak into passenger compartment (Ford) .....            | 384 |
| 1965 Ford integral heater - air-conditioning system .....                     | 501 |
| 66 Ford - Cold air entering passenger compartment .....                       | 563 |
| Falcon & Fairlane - A/C compressor vibration .....                            | 568 |
| 352-390 A/C vibration .....                                                   | 601 |

**TRUCK - ELECTRICAL****BRONCO**

|                                |     |
|--------------------------------|-----|
| Noisy starter engagement ..... | 570 |
|--------------------------------|-----|

**ECONOLINE**

|                                                                                                |         |
|------------------------------------------------------------------------------------------------|---------|
| Distributor cam lubricant .....                                                                | 10      |
| Radio ignition interference .....                                                              | 37      |
| Flashing charge indicator light and/or buzzing sound originating from alternator regulators .. | 78, 262 |
| Starter drive .....                                                                            | 154     |
| Failed alternator regulators caused by wiring defects .....                                    | 177     |
| Emergency warning flasher system operation .....                                               | 293     |
| Erratic horn operation .....                                                                   | 302     |
| Alternator - diagnosis of system malfunctions .....                                            | 324     |
| New alternator with internal radio noise suppression condenser .....                           | 429     |
| Battery acid odor .....                                                                        | 488     |
| Ignition system specifications .....                                                           | 578     |

**LIGHT**

|                                                                                                |         |
|------------------------------------------------------------------------------------------------|---------|
| Distributor cam lubricant .....                                                                | 10      |
| Radio ignition interference .....                                                              | 37      |
| Starter cable routing allowing contact with exhaust manifold (240, 300, 352 CID engines) ..... | 62      |
| Windshield wipers locking in extreme left position (F series) .....                            | 69      |
| Flashing charge indicator light and/or buzzing sound originating from alternator regulators .. | 78, 262 |
| Frame abrasion of positive battery cable (F Series) .....                                      | 128     |
| Starter drive .....                                                                            | 154     |
| Failed alternator regulators caused by wiring defects .....                                    | 177     |
| 1965 Autolite alternator rectifier assembly replacement .....                                  | 212     |
| Instrument panel bulb replacement .....                                                        | 284     |
| Electric wipers - linkage lockup .....                                                         | 290     |
| Emergency warning flasher system operation .....                                               | 293     |
| Erratic horn operation .....                                                                   | 302     |
| Alternator - front engine mount interference .....                                             | 304     |
| Alternator - diagnosis of system malfunctions .....                                            | 324     |
| Speedometer pointer - hang up .....                                                            | 379     |
| New alternator with internal radio noise suppression condenser .....                           | 429     |
| Alternator to regulator wiring - rerouting .....                                               | 486     |
| Rear lamp harness - connector corrosion .....                                                  | 493     |
| Noisy starter engagement .....                                                                 | 570     |
| Camper special and trailer wiring harness .....                                                | 584     |

**MEDIUM**

|                                                                                                  |         |
|--------------------------------------------------------------------------------------------------|---------|
| Distributor cam lubricant .....                                                                  | 10      |
| Starter cable routing allowing contact with exhaust manifold (240, 300, 352 CID engines) .....   | 62      |
| Windshield wipers locking in extreme left position (F series) .....                              | 69      |
| Flashing charge indicator light and/or buzzing sound originating from alternator regulators ..   | 78, 262 |
| Frame abrasion of positive battery cable (F series) .....                                        | 128     |
| Starter drive .....                                                                              | 154     |
| Failed alternator regulators caused by wiring defects .....                                      | 177     |
| 1965 Autolite alternator rectifier assembly replacement .....                                    | 212     |
| Transistor ignition system - shop manual error .....                                             | 277     |
| Electric wipers - linkage lockup .....                                                           | 290     |
| Emergency warning flasher system operation .....                                                 | 293     |
| Alternator - front engine mount interference .....                                               | 302     |
| New low air pressure warning switch .....                                                        | 303     |
| Alternator - diagnosis of system malfunctions .....                                              | 324     |
| New alternator with internal radio noise suppression condenser .....                             | 429     |
| Turn signal fuse .....                                                                           | 440     |
| Alternator to regulator wiring - rerouting .....                                                 | 486     |
| Discharged battery - flickering or blinking lights or erratic charge or alternator failure ..... | 554     |
| Eaton axle 2-speed solenoid .....                                                                | 565     |

**HEAVY & EXTRA HEAVY**

|                                                                                                |         |
|------------------------------------------------------------------------------------------------|---------|
| Distributor cam lubricant .....                                                                | 10      |
| Printed circuit board failures (61-64 Tilt Cab) .....                                          | 21      |
| Windshield wipers locking in extreme left position (F series) .....                            | 69      |
| Flashing charge indicator light and/or buzzing sound originating from alternator regulators .. | 78, 262 |
| Frame abrasion of positive battery cable (F series) .....                                      | 128     |
| Starter drive .....                                                                            | 154     |
| Failed alternator regulators caused by wiring defects .....                                    | 177     |
| 1965 Autolite alternator rectifier assembly replacement .....                                  | 212     |
| Transistor ignition system - shop manual error .....                                           | 277     |

**TRUCK - ELECTRICAL - (Cont'd.)**

|                                                                                                               |     |
|---------------------------------------------------------------------------------------------------------------|-----|
| Electric wipers - linkage lockup .....                                                                        | 290 |
| Emergency warning flasher system operation .....                                                              | 293 |
| Erratic horn operation .....                                                                                  | 302 |
| New low air pressure warning switch .....                                                                     | 303 |
| Alternator - diagnosis of system malfunctions .....                                                           | 324 |
| New alternator with internal radio noise<br>suppression condenser .....                                       | 429 |
| Turn signal fuse .....                                                                                        | 440 |
| Main wiring shorts (#14398) .....                                                                             | 480 |
| Three speed axle solenoids .....                                                                              | 539 |
| Discharged battery - flickering or blinking lights<br>or erratic charge indicator or alternator failure ..... | 554 |
| Eaton axle 2-speed solenoid .....                                                                             | 565 |

**PASSENGER CAR ENGINES****144 - 170 - 200 Family**

|                                                                                           |     |
|-------------------------------------------------------------------------------------------|-----|
| Distributor cam lubricant .....                                                           | 10  |
| Crankshaft oil seal replacement procedure .....                                           | 39  |
| Valve mechanism production deviated rocker arm .....                                      | 43  |
| Camshaft bearing specification revision .....                                             | 57  |
| Distributor specification for engines with<br>automatic transmission .....                | 58  |
| Heater hose to choke housing clamp<br>(omitted in production) .....                       | 74  |
| Ignition specification changes .....                                                      | 125 |
| Piston pin replacement procedure .....                                                    | 151 |
| Premature belt failures .....                                                             | 238 |
| Thermostat application .....                                                              | 241 |
| Ignition contact replacement .....                                                        | 147 |
| 65 Autolite alternator rectifier assembly<br>replacement .....                            | 212 |
| Positive crankcase ventilation system<br>maintenance .....                                | 279 |
| Broken brush holder attaching screw -<br>G. P. D. Alternators .....                       | 298 |
| Thermostat application chart (revised) .....                                              | 308 |
| Hydraulic valve lifter test .....                                                         | 323 |
| Diagnosis of obscure alternator system<br>malfunctions .....                              | 324 |
| Overheating .....                                                                         | 380 |
| Fuel pump noise diagnosis .....                                                           | 428 |
| Autolite alternators with internal radio noise<br>suppression capacitor (condenser) ..... | 429 |
| Revised alternator/water pump drive belts .....                                           | 432 |
| Cylinder head installation .....                                                          | 445 |
| Converting the 144 CID engine to 170 CID<br>engine .....                                  | 456 |
| Thermostat application .....                                                              | 463 |
| Thermactor exhaust emission control systems .....                                         | 464 |
| Camshaft bearing replacement .....                                                        | 465 |
| Accelerator linkage stabilizer rod .....                                                  | 468 |
| Repairing cylinder blocks with sand holes<br>or porosity .....                            | 477 |
| Accessory drive belts .....                                                               | 481 |
| Surge and rough idle .....                                                                | 526 |
| Noisy thermactor air pumps .....                                                          | 530 |
| Thermactor component identification .....                                                 | 536 |
| Poor fuel economy and/or rough idle .....                                                 | 564 |
| Poor fuel economy - automatic choke sticking .....                                        | 566 |

**223 Family**

|                                                                |     |
|----------------------------------------------------------------|-----|
| Crankshaft oil seal replacement procedure .....                | 39  |
| Premature belt failures .....                                  | 238 |
| Thermostat application .....                                   | 241 |
| Distributor cam lubricant .....                                | 10  |
| Ignition contact replacement .....                             | 147 |
| Positive crankcase ventilating system maintenance .....        | 279 |
| Thermostat application chart (revised) .....                   | 308 |
| Fuel pump noise diagnosis .....                                | 428 |
| Cleaning crankcase ventilation systems .....                   | 475 |
| Repairing cylinder blocks with sand holes<br>or porosity ..... | 477 |
| Accessory drive belts .....                                    | 481 |

**240 Family**

|                                                                                               |     |
|-----------------------------------------------------------------------------------------------|-----|
| Crankshaft oil seal replacement procedure .....                                               | 39  |
| Distributor specification for engines with<br>automatic transmissions (police and taxi) ..... | 59  |
| Ignition and engine specification (Shop Manual<br>Revision) .....                             | 76  |
| Revised valve rocker arm studs<br>(also see Article 190) .....                                | 96  |
| Revised tappet adjustment procedures .....                                                    | 100 |
| Engine dieseling .....                                                                        | 101 |
| Insufficient fan to radiator clearance .....                                                  | 108 |
| Camshaft gear noise .....                                                                     | 114 |
| Ignition specification changes .....                                                          | 125 |
| Piston pin replacement procedure .....                                                        | 151 |
| Premature belt failures .....                                                                 | 238 |
| Thermostat application .....                                                                  | 241 |
| Revised valve rocker arm studs<br>(also see Article 96) .....                                 | 190 |

**PASSENGER CAR ENGINES - (Cont'd.)**

|                                                                                           |     |
|-------------------------------------------------------------------------------------------|-----|
| Distributor cam lubricant .....                                                           | 10  |
| Ignition contact replacement .....                                                        | 147 |
| 65 Autolite alternator rectifier assembly<br>replacement .....                            | 212 |
| Alternator belt rubs A/C idler pulley .....                                               | 252 |
| Positive crankcase ventilation system<br>maintenance .....                                | 279 |
| Broken brush holder attaching screw -<br>G. P. D. alternators .....                       | 298 |
| Thermostat application chart (revised) .....                                              | 308 |
| Exhaust control valve assembly replacement<br>(240 1965) .....                            | 322 |
| Hydraulic valve lifter test .....                                                         | 323 |
| Diagnosis of obscure alternator system<br>malfunctions .....                              | 324 |
| New piston and pin assembly .....                                                         | 325 |
| Revised hydraulic tappet valve clearance<br>adjustment procedure .....                    | 351 |
| Rear engine oil seal .....                                                                | 367 |
| New rear crankshaft oil seal .....                                                        | 368 |
| Spark plug usage revisions (ref. art. 257<br>dated 4-19-65) .....                         | 371 |
| Overheating .....                                                                         | 380 |
| Valve rocker arm identification .....                                                     | 403 |
| Cylinder front cover bolt torque .....                                                    | 409 |
| Fuel pump noise diagnosis .....                                                           | 428 |
| Autolite alternators with internal radio noise<br>suppression capacitor (condenser) ..... | 429 |
| Hard cold engine starting - sticky choke .....                                            | 430 |
| Nylon fuel tube, fuel tank to pump .....                                                  | 431 |
| Revised alternator/water pump drive belts .....                                           | 432 |
| Cylinder head installation .....                                                          | 445 |
| Thermostat application .....                                                              | 463 |
| Thermactor exhaust emission control systems .....                                         | 464 |
| Noisy and/or squeaking valve rocker arm or<br>push rod action .....                       | 469 |
| Repairing cylinder blocks with sand holes<br>or porosity .....                            | 477 |
| Accessory drive belts .....                                                               | 481 |
| Noisy thermactor air pumps .....                                                          | 530 |
| Thermactor component identification .....                                                 | 536 |
| Hard hot starting .....                                                                   | 548 |
| New pistons to correct piston pin noise .....                                             | 555 |
| Poor fuel economy and/or rough idle .....                                                 | 564 |

**221 - 260 - 289 Family**

|                                                                                           |     |
|-------------------------------------------------------------------------------------------|-----|
| Distributor cam lubricant .....                                                           | 10  |
| Crankshaft oil seal replacement procedure .....                                           | 39  |
| Revised valve rocker arm studs<br>(also see Article 190) .....                            | 96  |
| Revised tappet adjustment procedure .....                                                 | 100 |
| Insufficient fan to radiator clearance .....                                              | 108 |
| Piston pin replacement procedure .....                                                    | 151 |
| Incorrect oil filler cap .....                                                            | 184 |
| New water pulley and power steering belt .....                                            | 232 |
| Premature belt failure .....                                                              | 238 |
| Thermostat application .....                                                              | 241 |
| Spark plug revision .....                                                                 | 257 |
| Delayed oil pressure at engine start up .....                                             | 189 |
| Valve rocker arm stud (also see Article 96) .....                                         | 190 |
| Ignition contact replacement .....                                                        | 147 |
| Relay to starter cable shorting (Mustang H. P.) .....                                     | 158 |
| Incorrect alternator and power steering<br>mounting bracket installation .....            | 187 |
| 65 Autolite alternator rectifier assembly<br>replacement .....                            | 212 |
| Positive crankcase ventilation system<br>maintenance .....                                | 279 |
| Broken brush holder attaching screw -<br>G. P. D. Alternators .....                       | 298 |
| Rough engine idle - 289-4V (Mustang) .....                                                | 307 |
| Thermostat application chart (revised) .....                                              | 308 |
| Proper grounding of battery ground cable .....                                            | 314 |
| Fuel pump eccentric bolt .....                                                            | 318 |
| Hydraulic valve lifter test .....                                                         | 323 |
| Diagnosis of obscure alternator system<br>malfunctions .....                              | 324 |
| New piston and pin assembly .....                                                         | 325 |
| Revised hydraulic tappet valve clearance<br>adjustment procedure .....                    | 351 |
| Carburetor flooding caused by needle cocking* .....                                       | 370 |
| Spark plug usage revisions (reference Article 257<br>dated April 19, 1965) .....          | 371 |
| Overheating .....                                                                         | 380 |
| New intake manifold to cylinder head<br>gaskets and seals .....                           | 396 |
| Valve rocker arm identification .....                                                     | 403 |
| Nylon secondary throttle control lever<br>(all 4V carburetors) .....                      | 404 |
| Fuel pump noise diagnosis .....                                                           | 428 |
| Autolite alternators with internal radio noise<br>suppression capacitor (condenser) ..... | 429 |
| Nylon fuel tube, fuel tank to pump .....                                                  | 431 |
| Revised alternator/water pump drive belts .....                                           | 432 |
| Cylinder head installation .....                                                          | 445 |

**PASSENGER CAR ENGINES — (Cont'd.)**

|                                                                     |     |
|---------------------------------------------------------------------|-----|
| Thermostat application .....                                        | 463 |
| Thermactor exhaust emission control systems .....                   | 464 |
| Noisy and/or squeaking valve rocker arm or<br>push rod action ..... | 469 |
| Cleaning crankcase ventilation systems .....                        | 475 |
| Repairing cylinder blocks with sand holes<br>or porosity .....      | 477 |
| Accessory drive belts .....                                         | 481 |
| Camshaft "chuck" noise .....                                        | 487 |
| New water pump assembly .....                                       | 517 |
| Noisy Thermactor air pumps .....                                    | 530 |
| Thermactor component identification .....                           | 536 |
| Flexible (rubber) fuel hose rubs on fuel<br>pump outlet tube .....  | 537 |
| Camshaft end play specifications .....                              | 585 |

\* (see supplement in September 17, 1965 issue)

**352 - 390 - 406 - 427 - 428 Family**

|                                                                                           |     |
|-------------------------------------------------------------------------------------------|-----|
| Distributor cam lubricant .....                                                           | 10  |
| Crankshaft oil seal replacement procedure .....                                           | 39  |
| Positive crankcase ventilating system test and<br>cleaning procedure .....                | 40  |
| Oil pan removal and installation<br>procedure revision .....                              | 61  |
| Engine specification and ignition<br>specification (Shop Manual Revision) .....           | 76  |
| Insufficient fan to radiator clearance .....                                              | 108 |
| Air conditioner compression vibrations .....                                              | 186 |
| Premature belt failures .....                                                             | 238 |
| Thermostat application .....                                                              | 241 |
| Holley carburetor specification .....                                                     | 196 |
| Ignition contact replacement .....                                                        | 147 |
| 65 Autolite alternator rectifier assembly<br>replacement .....                            | 212 |
| Misalignment of cylinder block hole in main<br>bearing upper insert .....                 | 276 |
| Positive crankcase ventilation system<br>maintenance .....                                | 279 |
| Broken brush holder attaching screw -<br>G. P. D. alternator .....                        | 298 |
| Thermostat application chart (revised) .....                                              | 308 |
| Hydraulic valve lifter test .....                                                         | 323 |
| Diagnosis of obscure alternator system<br>malfunctions .....                              | 324 |
| Carburetor flooding caused by needle cocking* .....                                       | 370 |
| Pinched secondary wiring (distributor) .....                                              | 374 |
| Overheating .....                                                                         | 380 |
| Nylon secondary throttle control lever<br>(all 4V carburetors) .....                      | 404 |
| Fairlane GT distributor advance curve .....                                               | 412 |
| Fuel pump noise diagnosis .....                                                           | 428 |
| Autolite alternators with internal radio noise<br>suppression capacitor (condenser) ..... | 429 |
| Nylon fuel tube, fuel tank to pump .....                                                  | 431 |
| Revised alternator/water pump drive belts .....                                           | 432 |
| Cylinder head installation .....                                                          | 445 |
| Thermostat application .....                                                              | 463 |
| Excessive oil consumption .....                                                           | 466 |
| Cleaning crankcase ventilation systems .....                                              | 475 |
| Repairing cylinder blocks with sand holes<br>or porosity .....                            | 477 |
| Accessory drive belts .....                                                               | 481 |
| Hard starting - 1964 & 65 T-Birds .....                                                   | 483 |
| Engine lifting eye - 1966 T-Birds .....                                                   | 511 |
| Excessive valve lash .....                                                                | 516 |
| Crankshaft identification .....                                                           | 519 |
| Cold engine stall on automatic transmission<br>engagement .....                           | 521 |
| Cylinder head, intake manifold and intake<br>manifold gasket application .....            | 528 |
| Noisy Thermactor air pumps .....                                                          | 530 |
| Thermactor component identification .....                                                 | 536 |
| Engine hesitates or stumbles on<br>acceleration (390-2V) .....                            | 562 |
| Excessive oil consumption, exhaust smoking<br>and plug fouling .....                      | 577 |
| Holley 4V carburetor for Fairlane GT and GTA .....                                        | 587 |
| Exhaust manifold restrictions .....                                                       | 589 |
| Engine vibration or unbalance (390 Engine) .....                                          | 592 |
| 1966 - 289 valve train changes .....                                                      | 608 |

\* (see supplement in September 17, 1965 issue)

**TRUCK ENGINES****140 - 170 Family**

|                                                            |     |
|------------------------------------------------------------|-----|
| Positive crankcase ventilation system<br>maintenance ..... | 279 |
| Hydraulic valve - lifter test .....                        | 323 |
| Crankcase oil refill - capacity .....                      | 426 |
| Fuel pump - noise diagnosis .....                          | 428 |
| Alternator/water pump - revised drive belts .....          | 432 |
| Converting 144 CID to 170 CID .....                        | 456 |
| Thermactor exhaust emission control systems .....          | 464 |

|                                                                |     |
|----------------------------------------------------------------|-----|
| Repairing cylinder blocks with sand holes<br>or porosity ..... | 477 |
| Surge and rough idle .....                                     | 526 |
| Thermactor component identification .....                      | 536 |
| Poor fuel economy and/or rough idle .....                      | 564 |

**223 - 262 Family**

|                                                                |     |
|----------------------------------------------------------------|-----|
| Positive crankcase ventilation system<br>maintenance .....     | 279 |
| Shop distributor calibration - manual<br>revisions .....       | 282 |
| Fuel pump - noise diagnosis .....                              | 428 |
| Alternator/water pump - revised drive belts .....              | 432 |
| Crankcase ventilation systems - cleaning<br>procedures .....   | 475 |
| Repairing cylinder blocks with sand holes<br>or porosity ..... | 477 |
| Thermactor component identification .....                      | 536 |

**240 - 300 Family**

|                                                                          |     |
|--------------------------------------------------------------------------|-----|
| Positive crankcase ventilation system<br>maintenance .....               | 279 |
| Engine governed RPM settings .....                                       | 286 |
| Camshaft gear noise .....                                                | 306 |
| Connecting rod revisions .....                                           | 320 |
| Hydraulic valve - lifter test .....                                      | 323 |
| New piston and pin assembly .....                                        | 325 |
| Hydraulic tappet valve clearance - revised<br>adjustment procedure ..... | 351 |
| Rear engine oil seal .....                                               | 367 |
| New rear crankshaft oil seal .....                                       | 368 |
| Spark plug usage (article supersedes<br>#257 and #125) .....             | 371 |
| Fuel pump - noise diagnosis .....                                        | 428 |
| Alternator/water pump - revised drive belts .....                        | 432 |
| Front cylinder cover - bolt torque .....                                 | 409 |
| Cylinder Head installation - all V8's .....                              | 445 |
| Thermactor exhaust emission control systems .....                        | 464 |
| Noisy valve rocker arm or push rod action .....                          | 469 |
| Repairing cylinder blocks with sand holes<br>or porosity .....           | 477 |
| Thermactor component identification .....                                | 536 |
| Front engine support bracket .....                                       | 538 |
| Hard hot starting .....                                                  | 548 |
| New pistons to correct piston pin noise .....                            | 555 |
| Poor fuel economy and/or rough idle .....                                | 564 |

**302 - 332 Family**

|                                                                |     |
|----------------------------------------------------------------|-----|
| Positive crankcase ventilation system<br>maintenance .....     | 279 |
| Fuel pump - noise diagnosis .....                              | 428 |
| Alternator/water pump - revised drive belts .....              | 432 |
| Cylinder head installation - all V8's .....                    | 445 |
| Repairing cylinder blocks with sand holes<br>or porosity ..... | 477 |
| Thermactor component identification .....                      | 536 |

**330 - 352 - 361 - 391 Family**

|                                                                                           |     |
|-------------------------------------------------------------------------------------------|-----|
| Positive crankcase ventilation system<br>maintenance .....                                | 279 |
| Engine governed RPM settings .....                                                        | 286 |
| Front engine crossmember failure - 8 cylinder<br>school bus (B-500 to B-750 series) ..... | 291 |
| Hydraulic valve - lifter test .....                                                       | 323 |
| New cold weather starting procedure .....                                                 | 417 |
| Revised engine specifications .....                                                       | 447 |
| Oil consumption .....                                                                     | 460 |
| Crankcase ventilation system-cleaning<br>procedures .....                                 | 475 |
| Cylinder head installation - all V8's .....                                               | 445 |
| Repairing cylinder blocks with sand holes<br>or porosity .....                            | 477 |
| Thermactor component identification .....                                                 | 536 |
| Excessive oil consumption, exhaust smoking<br>and spark plug fouling .....                | 577 |

**401 - 477 - 534 Family**

|                                                                             |     |
|-----------------------------------------------------------------------------|-----|
| Shutterstat by-pass - correction of<br>article #138, February 1, 1965 ..... | 138 |
| Positive crankcase ventilation system<br>maintenance .....                  | 279 |
| Engine governed RPM settings .....                                          | 286 |
| Fuel pump - noise diagnosis .....                                           | 428 |
| Alternator/water pump - revised drive belts .....                           | 432 |
| Cylinder head installation - all V8's .....                                 | 445 |
| Carburetor air cleaner - extra capacity .....                               | 448 |
| Camshaft removal .....                                                      | 455 |
| Repairing cylinder blocks with sand holes<br>or porosity .....              | 477 |
| Thermactor component identification .....                                   | 536 |

**TRUCK ENGINES — (Cont'd.)**Dagenham Diesel

|                                                      |     |
|------------------------------------------------------|-----|
| Cylinder head installation - all V8's .....          | 445 |
| New self locking vibration damper bolts .....        | 472 |
| Air compressor mounting failures .....               | 508 |
| Fuel solenoid control mounting bracket failure ..... | 591 |

Cummins Diesel

|                                                |          |
|------------------------------------------------|----------|
| Engine governed RPM settings and speeds .....  | 286, 411 |
| Cylinder head installation - all V8's .....    | 445      |
| New air cleaner - to prevent water entry ..... | 452      |
| Air cleaner oil cup assembly .....             | 512      |
| Air cleaners (V-6) .....                       | 594      |

**NOISE, VIBRATION AND HARSHNESS ITEMS**Ford

|                                                                                                             |     |
|-------------------------------------------------------------------------------------------------------------|-----|
| Power steering hissing noise .....                                                                          | 25  |
| Power steering noise transmitted into passenger compartment .....                                           | 26  |
| Air conditioner vibration problems .....                                                                    | 29  |
| Tip-in moan or vibration periods at constant speeds .....                                                   | 30  |
| High speed driveline vibrations .....                                                                       | 104 |
| Air conditioner compressor vibrations (Chicago built units) .....                                           | 186 |
| Improperly machined output shaft rear thrust face generating a high pitched buzzing or grinding noise ..... | 215 |
| Rear shock absorber noise .....                                                                             | 256 |
| Driveshaft balancing identification .....                                                                   | 416 |
| Fuel pump noise diagnosis .....                                                                             | 428 |
| Starter noise .....                                                                                         | 525 |
| Noisy Thermactor air pumps .....                                                                            | 530 |
| New pistons to correct piston pin noise .....                                                               | 555 |
| Engine noise or odors entering passenger compartment .....                                                  | 563 |
| 390 engine unbalance or vibration .....                                                                     | 592 |
| 352-390 A/C vibration .....                                                                                 | 601 |

Fairlane

|                                                                         |     |
|-------------------------------------------------------------------------|-----|
| Power steering hissing noise .....                                      | 25  |
| High speed driveline vibrations .....                                   | 104 |
| Speedometer driven gear ticking noise .....                             | 200 |
| Air/conditioner Vibration (6 cylinder, Mustang, Fairlane, Falcon) ..... | 363 |
| Driveshaft balancing identification .....                               | 416 |
| Fuel pump noise diagnosis .....                                         | 428 |
| Body vibration damper installation .....                                | 509 |
| Starter noise .....                                                     | 525 |
| Noisy Thermactor air pumps .....                                        | 530 |
| Rear seat boom vibrations - 30-40 mph .....                             | 540 |
| Gear shift lever and/or steering column rattle .....                    | 557 |
| A/C compressor vibration .....                                          | 568 |
| 390 engine unbalance or vibration .....                                 | 592 |

Falcon

|                                                                             |     |
|-----------------------------------------------------------------------------|-----|
| Power steering hissing noise .....                                          | 25  |
| High speed driveline vibrations .....                                       | 104 |
| Air/conditioner Vibration (6 cylinder, Mustang, Fairlane, Falcon) .....     | 363 |
| Driveshaft balancing identification .....                                   | 416 |
| Fuel pump noise diagnosis .....                                             | 428 |
| Starter noise .....                                                         | 525 |
| Noisy Thermactor air pumps .....                                            | 530 |
| Gear shift lever and/or steering column rattle .....                        | 557 |
| Exhaust "boom" noise and/or vibration at 25-35 mph under acceleration ..... | 558 |
| A/C compressor vibration .....                                              | 568 |

Thunderbird

|                                                                                                              |     |
|--------------------------------------------------------------------------------------------------------------|-----|
| Power steering hissing noise .....                                                                           | 25  |
| Air conditioner vibration problems .....                                                                     | 29  |
| Dynamically balancing wheel and tire assembly on vehicles with disc brakes .....                             | 56  |
| High speed driveline vibrations .....                                                                        | 104 |
| Disc brake creep groan noise .....                                                                           | 104 |
| Improperly machined output shaft rear thrust face, generating a high pitched buzzing or grinding noise ..... | 215 |
| Driveshaft balancing identification .....                                                                    | 416 |
| Fuel pump noise diagnosis .....                                                                              | 428 |
| Driveshaft yoke spline lubricant .....                                                                       | 473 |
| Starter noise .....                                                                                          | 525 |
| Noisy Thermactor air pumps .....                                                                             | 530 |
| 390 engine unbalance or vibration .....                                                                      | 592 |

Mustang

|                                      |    |
|--------------------------------------|----|
| Power steering hissing noise .....   | 25 |
| Transmission shift lever noise ..... | 27 |

|                                                                                  |     |
|----------------------------------------------------------------------------------|-----|
| Dynamically balancing wheel and tire assembly on vehicles with disc brakes ..... | 56  |
| Convertible cowl shake and/or vibrations .....                                   | 86  |
| High speed driveline vibrations .....                                            | 104 |
| Disc brake creep-groan noise .....                                               | 105 |
| Mustang - High noise level of (Arvinode dual exhaust system) .....               | 315 |
| Mustang - Dual exhaust system (65-1/2 289 4V H. P.) .....                        | 328 |
| Mustang - Single exhaust system noise (65-289 4V) .....                          | 353 |
| Air/conditioner Vibration (6 cylinder, Mustang, Fairlane, Falcon) .....          | 363 |
| Driveshaft balancing identification .....                                        | 416 |
| Fuel pump noise diagnosis .....                                                  | 428 |
| Transmission shift lever buzz .....                                              | 449 |
| Starter noise .....                                                              | 525 |

TruckEconoline

|                                          |     |
|------------------------------------------|-----|
| Gear rattle - 3 speed transmission ..... | 490 |
|------------------------------------------|-----|

Light

|                                                                   |          |
|-------------------------------------------------------------------|----------|
| Torsional vibration - 4 speed transmission .....                  | 300, 334 |
| Gear rattle and shift fork noise - new process transmission ..... | 382, 439 |
| Clutch shudder - low and reverse - 352 CID .....                  | 474      |
| Starter noise .....                                               | 525      |
| Clutch shudder low and reverse .....                              | 553      |

**SPECIAL SERVICE TOOLS**

|                                                                                                               |     |
|---------------------------------------------------------------------------------------------------------------|-----|
| Modification of right height tool T65-P-3000-B or C .....                                                     | 6   |
| Modification of front end tool T62F-3000-B .....                                                              | 7   |
| Modification of front end tool T57P-3006-A .....                                                              | 11  |
| Special speedometer cable hex head nut wrench .....                                                           | 8   |
| Special "Rally Pac" screw driver .....                                                                        | 45  |
| Special power steering pump pulley remover .....                                                              | 49  |
| Special tapered socket for C4 transmission clutch race bolt .....                                             | 66  |
| Bullet terminal removal from turn signal switch multiple connector .....                                      | 77  |
| Special tool for removing Mustang rear axle filler plug .....                                                 | 93  |
| Engine stand .....                                                                                            | 132 |
| Special serrated socket for Dagenham Diesel pump valve holder .....                                           | 169 |
| New compression tester for Dagenham Diesels .....                                                             | 170 |
| Special tool for removal of steering arms from sector shafts .....                                            | 203 |
| Special tool to remove super duty engine crankshaft dampers .....                                             | 204 |
| Special tools for 1951-58 Ford-O-Matic and Cruise-O-Matic .....                                               | 205 |
| Improper usage of T63L-10300-B .....                                                                          | 206 |
| Special power steering pump pulley remover .....                                                              | 207 |
| Special voltage regulator thermometer .....                                                                   | 208 |
| Special Lincoln pinion front bearing cup remover .....                                                        | 220 |
| Special adapter kit to remove and replace rear spring front bushings (Falcon, Comet, Mustang, Fairlane) ..... | 221 |
| Special Lincoln rear axle pinion oil seal tool .....                                                          | 223 |
| Special Lincoln rear axle front bearing tool .....                                                            | 224 |
| Special tool for rear spring front eye bushings (Falcon, Comet, Mustang, Fairlane) .....                      | 225 |
| Special tool for Lincoln rear spring front eye bushings .....                                                 | 226 |
| Special torque checking tool for Falcon, Mustang and Comet locking differentials .....                        | 227 |
| Special Lincoln rear axle pinion rear bearing remover .....                                                   | 228 |
| Special velocity governor wrench assembly .....                                                               | 94  |
| Tandem equalizer beam bushing service tool .....                                                              | 259 |
| Special service tool - service part and number change .....                                                   | 260 |
| Special Mustang band adjusting tool .....                                                                     | 268 |
| Correction to special tool part number in 268 (May 10, 1965) .....                                            | 268 |
| Special crowfoot wrench for vacuum T. V. diaphragm .....                                                      | 280 |
| New special service tool T6PP-10B 960-A .....                                                                 | 283 |
| Rotunda auto radio test tool (T65P-18805-A) .....                                                             | 389 |
| Special service tools - ownercard program .....                                                               | 437 |
| 1966 tool silhouette and hook package .....                                                                   | 500 |
| Disc brake rotor resurfacing .....                                                                            | 575 |

**MISCELLANEOUS OILS, LUBRICANTS, FLUIDS & CHEMICALS**

|                                                                  |     |
|------------------------------------------------------------------|-----|
| Distributor cam lubricant .....                                  | 10  |
| Automatic transmission fluids that meet Ford specification ..... | 155 |
| Quick reference chart Rotunda oil and lubrication .....          | 319 |
| Fuel odor in 1965 Ford luggage compartment .....                 | 377 |
| Automatic transmission fluids that meet Ford specification ..... | 413 |
| Driveshaft yoke spline lubricant .....                           | 473 |
| Water leaks - repair sealant .....                               | 479 |